
## sPHENIX Engineering Installation and Integration




#### **Engineering Effort**

sPHENIX currently has ~ 20 engineers working working on designs, R&D and prototyping for:

- Decommissioning
- Magnet
- Detector subsystems (both mechanical and electronic)
- Integration
- Installation
- Infrastructure
- E, S & H

#### **Installation Plan**



#### Specifications/Requirements: sPHENIX Integration and Installation

- IR & AH Floor Loading Limits: 4000 psi, max
- Positional precision: 0.5 mm,
   Angular precision: 10 milliradian (roll, pitch and yaw)
- Installation to be accomplished in the Assembly Hall (40 ton and 5 ton overhead cranes)
- Assembly to be prepared for magnet mapping in Interaction Region (IR) after Outer HCal is installed, then returned to Assembly Hall to complete detector installations.
- Overall size requirements The complete sPHENIX assembly, including magnet valve box stack and all electronics racks, must fit through the sPHENIX sill on the existing sPHENIX rail system


#### sPHENIX Assembly and Installation Tooling and Fixtures


We have identified all of our significant tooling needs:

- Central Pedestal (CP): (standard lifting tools for CP base and rollers, cradle, support posts, bridge, access stairs), alignment tools for rollers and cradle.
- Outer HCal: module holding fixture (4), indexed lifting/installation fixture, alignment tools, temporary inner & outer support assembly fixtures
- **Inner HCal**: module holding fixture (4), module lifting fixture, assembly indexed/rotating fixture and insertion beam and insertion beam lifting fixture, alignment tools
- **EMCal:** module handling fixture (8), rail alignment tool, indexed lifting/installation fixture
- **Tracking**: Handling fixture (2), alignment tool, installation tool
- SC Magnet: Lifting fixture (spreader bar), alignment tool, stack handling/lifting tool
- **Infrastructure**: beampipe alignment tools/fixtures, bakeout tools/fixtures


#### Install the Central Pedestal (CP) Base

- Gather and stage CP Base components (base platform sections, Hillman Rollers, X-Y alignment details, cradle arcs)
- Assemble lower platform
- Install and position cradle arcs and cross members
- Survey cradle arcs, adjust alignment and indexing, weld in place
- Position, align and install Hillman Rollers






#### Install the Lower Half of the Outer HCal



#### Magnet Preparation and Installation




- Install SC-magnet inside of bottom 1/2 of Outer HCal cylinder.
- Rotate into proper position


#### Eventual service to SC-magnet.


- Provide DC Power Supply that is compatible with the requirements of the coil (4596A @ 20V -> 1.5 T Central Field);
- Provide a Magnet Quench Detection System, Dump Resistor, and Switch;
- Provide an operating Cryogenic System with associated support equipment (i.e. Turbo Vacuum Pump, Cryogenic Lines and Connectors, Controls and Communications, Pressure Relief Devices and Lines, Cryogenic Transfer Lines)
- Provide a Magnet Mapping Device and measure the magnetic field

### Install the rest of the Outer HCal, Upper Platform & Magnet Stack





- Install upper platform support columns and bracing
- Install SC magnet Stack
- Install Flux return End Caps
- Into IR for Magnet mapping/Test then Back to AH






#### Inner HCal







- Transport Inner HCal completed modules to AH
- Test to make sure electronics are intact after transport
- Assemble Inner HCal in rotating assembly fixture 1 module at a time
- Final adjustments and lock
- Install Inner HCal mounting supports
- Install beam extension
- Install the full Inner Hcal, align and attach to the Inner HCal mounting supports.
- Install patch panels, cables, and route to racks
- Test all connections




#### **EMCal**


- Transport modules to AH
- Test to make sure electronics are intact after transport.
- One by one Insert and align the 32 south EMCal modules using the indexed insertion tool.
- Repeat for north side
- Make final alignment adjustments and secure and lock all modules in place.
- Install patch panels, cables, services and route to racks
- Test all connections








#### **Detector Cross Section**



#### Integration




#### **Integration Requirements**

- Define overall envelope for sPhenix. (DWG# SP00-000-000).
  - Includes relevant existing infrastructure.
    - Tracks, IR walls, MuID, Crane hooks etc.
  - Envelope to include nuts bolts cables.
  - Only collaboration can change detector envelopes.
  - Stay clear regions between detectors for clearance & installation.
  - Ensure everything fits.
  - Define detector attachment points.
- Cable Management & Routing.
  - HV, LV, Signal & Cooling requirements
  - Provided to Integration by subsystem for inclusion in overall envelope.


#### **SPHENIX Envelope Control Drawing**

# NOTES: 1. NOTED DIMENSIONS ARE MAXIMUM SIZE. ALL SERVICES, NUTS, BOLTS & OTHER DETECTOR COMPONENTS SHALL NOT EXCEED THESE DIMENSIONS. 2. ALL DIMENSIONS ARE IN mm[inch]. SHIELD WALL FOR REFERENCE ACTUAL OPER ACTUAL OPER


- AUTOCAD DRAWING
- SHOWS RELEVANT EXISTING INFRASTRUCTURE
- ONGOING EFFORT FOR SPHENIX



#### sPHENIX Overall Size and Shield Wall Opening




#### Inner HCAL Electroncis and Cable Routing




#### **Allocating Space for Services**

Inner HCal ½ sector Class II mockup (dimensionally accurate/non-functional)






#### Infrastructure at 1008 for sPHENIX



Provide the detector Central Pedestal Support and Interconnecting hardware and support structures.

- 1. Support Pedestal, rollers, vertical and horizontal positioning assembly
- 2. End Ring for transitional support of the Inner Hcal Assembly to the Outer Hcal
- 3. Provide Electronics Bridge and Access Stairs
- 4. Magnet Pole Tips (Flux return endcaps)





**Existing Facility** 

- **Conventional Systems**
- A/C Power
- Piping Supports (Cryo Pipe)
- Cable Tray
- Cooling Water
- Assembly Building/Control Room/Support Buildings
- HSSD, Leak Detection, Pass System, ODH
- Gas Distribution System (if required)



**Existing Water System** 



**Existing Distribution** 



**Existing Power** 



**Existing Power** 

#### Infrastructure Specification/Requirements

- Pole Tips
  - 204" OD x 24" ID x 12" Thick
  - Material C1006 Magnet Steel
  - Detector Accessibility Requirements Extended Maintenance (1week)
- Support Ring
  - Material Stainless, 400 Series
  - Load Requirements Transfer support loads from Inner HCal/EMCal to Outer Hcal
- Access Bridge
  - Accommodate Racks, Cryo Valve Box, Dewars (2), Controls
  - Design Floor Load Requirement 150 PSF
- Cradle and Base
  - Design Load Requirement 628T
  - Detector Verti./Horiz. Alignment Requirements ±0.020 in. Vert/Horiz. , ±0.050 in. longitudinal. (proposed)
  - Detector Travel Speed Requirement 1'/min. (proposed)
- Vacuum Pipe
  - Reuse of 31.5 inch long beryllium section
- Conventional Systems
  - Cooling Water provide 2 gpm @ 50F Supply 2 KW/Rack
  - HVAC 68F/50%RH
  - Existing 480V, 1200A Buss
  - TPC Gas System (if required)
- Cryogenic systems and magnet support
  - Magnet power supply
  - Quench protection system
  - Cryo supply and controls. Integrated with the RHIC cryo system

#### Summary

- There is significant engineering progress in support of sPHENIX
- Thanks to the hard work of our team of engineers we have developed initial plans for PHENIX decommissioning, sPHENIX magnet testing/installation, integration, installation and infrastructure support.
- Plans are underway to take full advantage of the existing infrastructure in the 1008 complex for sPHENIX.
- Though a lot of detailed work remains, the work to date reveals no major engineering challenges for the integration, installation and infrastructure.